

# 1997

Photos and captions provided by Alan Lewis.

The first two photos involve the re-furbishing of two sets of gates by a Boston company in 1997.

The other three involve the re-furbishing of two other sets of gates by Bonneville Dam personnel in 1999.



Above: Photo #1 shows a leaf of Gate Number 5 that has just been pulled out of the canal. It was decided to do the re-furb work in a yard on the Columbia River.

## 1997 & 1999

Below: Photo #2 shows a tug pushing a barge carrying two leaves, leaving the canal on it's way down stream (to that yard).



Above: Photo #3 shows a leaf of Gate Number 3 that has just been pulled out of the canal. This time it was decided to do the re-furb work on the picnic area adjacent to the canal.

1999



Left: Photo #4 shows the leaf being lowered onto the work area.

Right: Photo #5 shows the leaf being inspected.

